

Dump File	Crash Time	Bug Check String	Bug Check Code	Parameter 1	Parameter 2	Parameter 3	Parameter 4	Caused By Driver	Caused By Address	File Description	Product Name
0729018-19047-01.dmp	29.7.2018 14:19:25	KERNEL_DATA_INPAGE_ERROR	0x0000007a	ffff66c40007358	fffff8b1c0000185	000000001720878...	ffff880435520099	atapport.sys	atapport.sys+1e93c	ATAPI Driver Extension	Microsoft® Windo
072918-14492-01.dmp	28.7.2018 12:41:13	MEMORY_MANAGEMENT	0x0000001a	000000000000050...	0000000000000000	0000000000002ae...	ffff8801156eald	ntoskrnl.exe	atapport.sys+735c0	NT Kernel & System	Microsoft® Windo
072818-13462-01.dmp	28.7.2018 23:03:20	DRIVER_IRQL_NOT_LESS_OR_EQUAL	0x000000d1	0000000000000000...	0000000000000000...	0000000000000000...	NETIO.SYS	NETIO.SYS+25ald	atapport.sys+25ald	Network I/O Subsystem	Microsoft® Windo
072818-13993-01.dmp	28.7.2018 22:50:22	NTFS_FILE_SYSTEM	0x00000024	000000000001904fb	ffff880039193628	ffff88001192e680	NTfs.sys	NTfs.sys+fa3a	atapport.sys+fa3a	NT File System Driver	Microsoft® Windo
072818-21606-01.dmp	28.7.2018 20:31:42	PAGE_FAULT_IN_NONPAGED_AREA	0x00000050	ffff880005997018	0000000000000000...	ffff88000394eb05	atapport.sys	atapport.sys+f74d	atapport.sys+f74d	ATAPI Driver Extension	Microsoft® Windo
072818-24211-01.dmp	28.7.2018 15:39:26	PAGE_FAULT_IN_NONPAGED_AREA	0x00000050	ffff88032824c20	0000000000000000...	ffff8800038ad254	ntoskrnl.exe	ntoskrnl.exe+735c0	atapport.sys+735c0	NT Kernel & System	Microsoft® Windo

Filename	Address In St...	From Address	To Address	Size	Time Stamp	Time String	Product Name	File Description	File Version	Company	Full Path
atapport.sys	atapport.sys+1e93c	ffff8800064d000	ffff88000670000	0x0002a000	0x55f169b5	5.8.2013.340245	Microsoft® Wind...	ATAPI Driver Exten...	6.1.7601.16385 (wi...	Microsoft Corpora...	C:\Windows\sys...
ntoskrnl.exe	ntoskrnl.exe+e6442	ffff88000380c000	ffff880003d7000	0x0005e8000	0x53efca65	22.7.2015.1852553	Microsoft® Wind...	NT Kernel & System	6.1.7601.16385 (wi...	Microsoft Corpora...	C:\Windows\sys...
hal.dll		ffff880003d7000	ffff880003e40000	0x00049000	0x4cef7d69	20.11.2010.15:00:25	Microsoft® Wind...	Hardware Abstract...	6.1.7601.17514 (wi...	Microsoft Corpora...	C:\Windows\sys...
kdcom.dll		ffff88000b69000	ffff88000b6b3000	0x0000a000	0x4d4488061	5.2.2011.18:52:49	Microsoft® Wind...	Serial Kernel Debu...	6.1.7601.17556 (wi...	Microsoft Corpora...	C:\Windows\sys...
incupdate.GenuineIntel.dll		ffff88000c41000	ffff88000c6f0000	0x0004f000	0x4cef7377	20.11.2010.15:03:51	Microsoft® Wind...	Intel Microcode U...	6.1.7601.17514 (wi...	Microsoft Corpora...	C:\Windows\sys...
PSHEd.dll		ffff88000c6f0000	ffff88000d040000	0x00014000	0x455b6d27	14.7.2009.3:32:23	Microsoft® Wind...	Platform Specific ...	6.1.7600.16385 (wi...	Microsoft Corpora...	C:\Windows\sys...
CLEFS.SYS		ffff88000d040000	ffff88000d62000	0x0005e000	0x546f7a28	4.3.2015.5:21:12	Microsoft® Wind...	Common Log File ...	6.1.7600.16385 (wi...	Microsoft Corpora...	C:\Windows\sys...
ClDll		ffff88000d62000	ffff88000dd7000	0x00075000	0x53acd125	27.6.2014.4:04:21	Microsoft® Wind...	Code Integrity Mo...	6.1.7601.16950 (wi...	Microsoft Corpora...	C:\Windows\sys...
WdF01000.sys		ffff88000e80000	ffff88000f42000	0x0002c000	0x51c51641	22.6.2013.5:13:05	Operacni systém ...	Kernel Mode Drive...	1.11.9200.16384 (w...	Microsoft Corpora...	C:\Windows\sys...
WDFLDR.SYS		ffff88000f42000	ffff88000f52000	0x00010000	0x5010ab70	26.7.2012.4:29:04	Microsoft® Wind...	Kernel Mode Drive...	6.1.7600.16384 (w...	Microsoft Corpora...	C:\Windows\sys...
ACPI.sys		ffff88000f52000	ffff88000f69000	0x00057000	0x4cef9294	20.11.2010.11:19:16	Microsoft® Wind...	ACPI Driver for NT	6.1.7600.16385 (wi...	Microsoft Corpora...	C:\Windows\sys...
WMI.LIB.SYS		ffff88000f69000	ffff88000fb2000	0x00009000	0x45b0c117	14.7.2009.1:19:51	Microsoft® Wind...	WMI supp...	6.1.7600.16385 (wi...	Microsoft Corpora...	C:\Windows\sys...
misasdr.sys		ffff88000fb2000	ffff88000fbcd000	0x0000a000	0x45b0c0fe	14.7.2009.1:19:26	Microsoft® Wind...	ISA Driver	6.1.7600.16385 (wi...	Microsoft Corpora...	C:\Windows\sys...
pcl.sys		ffff88000fbcd000	ffff88000fd0000	0x00003000	0x4cef928f	20.11.2010.11:19:11	Microsoft® Wind...	NT Plug and Play ...	6.1.7600.16385 (wi...	Microsoft Corpora...	C:\Windows\sys...
vdhroot.sys		ffff88000fd0000	ffff88000fd0000	0x0000d000	0x45b0c0ad	14.7.2009.2:01:31	Microsoft® Wind...	Kořenový enumer...	6.1.7600.16385 (wi...	Microsoft Corpora...	C:\Windows\sys...
partmgr.sys		ffff88000fd0000	ffff88000fe15000	0x00015000	0x46f41c1	17.3.2012.7:06:09	Microsoft® Wind...	Partition Manage...	6.1.7600.16385 (wi...	Microsoft Corpora...	C:\Windows\sys...
volmgr.sys		ffff88000fe15000	ffff88000fe2a000	0x00015000	0x4cef92ad	20.11.2010.11:19:28	Microsoft® Wind...	Volume Manager ...	6.1.7601.17514 (wi...	Microsoft Corpora...	C:\Windows\sys...
volmgr.sys		ffff88000fe2a000	ffff88000fe5c000	0x0005c000	0x00000000	15.7.2015.18:44:37	Microsoft® Wind...	Volume Manager ...	6.1.7600.16385 (wi...	Microsoft Corpora...	C:\Windows\sys...
mountmgr.sys		ffff88000fe5c000	ffff88000fe64000	0x0001a000	0x5a586df5	14.7.2009.1:19:47	Microsoft® Wind...	Mount Point Man...	6.1.7601.16933 (wi...	Microsoft Corpora...	C:\Windows\sys...
atap.sys		ffff88000fe64000	ffff88000fe64000	0x00009000	0x45b0c113	20.11.2010.12:33:58	Microsoft® Wind...	ATAPIIDE Minipor...	6.1.7600.16385 (wi...	Microsoft Corpora...	C:\Windows\sys...
msahci.sys		ffff88000fe67000	ffff88000fe70000	0x0000b000	0x4cef7a16	14.7.2009.1:19:48	Microsoft® Wind...	MS AHCI 1.0 Stand...	6.1.7601.17514 (wi...	Microsoft Corpora...	C:\Windows\sys...
PCIDEX.SYS		ffff88000fe70000	ffff88000fe70000	0x00010000	0x45b0c114	14.7.2009.1:19:48	Microsoft® Wind...	PCIDE Bus Driver ...	6.1.7600.16385 (wi...	Microsoft Corpora...	C:\Windows\sys...